G.R.S. IX-5]

Reserve

Previous references.

1922-23

(Misc-)

File No. 35-22

Serial Nos. 1-4

Later references.
35-22 & 108
228-28 1-2

GENERAL AND REVENUE SECRETARIAT.

Serial Nos. 1-4

Part B for September 22

SUBJECT.

Estimate for the installation of a lightning conductor to the Sri Mallikarjunaswami temple at Bettadapur, Hunsur Tk.

81-4) The Ch. Engr. of Mysore.
The D.C. Mysore Dist.
The Tahsildar
No 1147-51 dt 5-9-22.

G. R. S. III—1] 1922-23.

GENERAL AND REVENUE SECRETARIAT.

(Inwards)

NOTES.

File No. 35-22.

FILE HEADING.

Estimate for the installation of a lightning conductor to the Sri MalliKanjimaduvany temple at Bettadapur, Hunsur Taluk.

From

From the Chief Engineer of Mysore.

No. B. 2/6-2m(53)-22 Dated 10.7.22. Received 15.7.22.

Diary No. 238	Enclos. 6 Spare Copies.	Serial No. 1

BRIEF ABSTRACT OF LETTER.

Forwards for sanction an estimate for Rs. 125-4 for the above work received from the Chief Electrical Engineer who reports that the temple being situated on a high hill has been very seriously damaged by frequent strokes of lightning discharges to which it is very frequently exposed and that if precau-

NOTES AND ORDERS.

tion is not taken to guard the temple against danger it is prone to considerable damage.

The temple is stated to be a minor Inwards institution.

The estimate has been countersigned by the Chief Electrical Engineer, Executive Engineer, Mysore Division

NOTES—First Sheet.

2.5.

G. R. S. III-21

General and Revenue Secretariat.

Mysore. File No. 35 - 22 of 19

Serial No.

and the Deputy Commr", Mysore Dt.
Yuked" for orders.
MAS. This is a minor institution
177-22. and the amt at its credit
Cannot be ascertained from the
Comptroller's office. If appd the
Dy. Comr will be asked to state
the amt at the credit of the
instn.

BG
15/7/22

Draft letter to the D.C. sent
MAS.
15-7-22. BG 21/7/22

2 To.

NOTE—Contn. sheet.

G. R. S. III-21

70

General and Revenue Secretariat.

Muz. File No. 35 of 1922.

Serial No.	
3	From The Dy Commr, Mysore Dt. No. L. Dis. 25/22-23 Muz. dt. 18.8.22. — States that it is reported by the Sub-Division officer, Mysore, that the installation of a lightning conductor to the above temple is necessary and may be installed and that a sum of Rs. 4832-3-0 is available at the credit of the institution.
	[illegible]
	22 31/8/22
	[illegible] 11/9/22
	Comp approved Pell 5.9.22 — 14/9/22 [illegible]
4	[illegible]

NOTE—Contn. sheet

SUPERINTENDING ENGINEER'S OFFICE
Regd. No. 219
12 JUL 1922
MYSORE P. W. DEPT.

No. 36 /EM(53N-22)

1 Estt
1 Sketch
1 Duplicate copy

To 3/ Govt.

Office of the Superintending Engineer,
Western Circle, Mysore,
Dated Mysore, 7th July 1922.
10

The Secretary to Government,
Muzrai Department, Bangalore.

Through

The Chief Engineer of Mysore,
Bangalore.

Sir,

I have the honour to forward herewith for favour of sanction, an estimate amounting to Rs.1254 for installing lightning conductor to the Mallikarjunaswami Temple at Pattadakal, Hunsur Taluk duly countersigned by the Deputy Commissioner, Mysore District.

Copy of letter No...35454-114 dated 23-3-1919 from the Chief Electrical Engineer to the Executive Engineer, Mysore Division, is herein enclosed for information, wherein the necessity of the lightning conductor has been explained.

Recd by me
11.7.22

I have the honour to be,
Sir,
Your most obedient servant,

Superintending Engineer,
Western Circle.

K.N.

Camp Channekinkatti
8.7.22

No B389 dated 15 July 1922.

238
22-23
Muzr
35-22-1

Passed on

In Chief Engineer
13
12/7/22 of Mysore

Letter No.M.35454-114 dated the 27th March 1919 from the Chief Electrical Engineer to the Government of Mysore, to the Executive Engineer, Mysore Division.

LIGHTNING CONDUCTOR TO MALLIKARJUNASWAMI TEMPLE AT BETTADAPUR.

With reference to your letter No.1396 dated the 25th July 1918 we wish to inform you that our General Electric Inspector Faraday visited the place during the month. A copy of the letter of the 24th instant which is self explanatory, is herewith enclosed. We also enclose an estimate amounting to Rs.1,254 for the above work. A rough sketch is also sent, which may be returned along with the estimate after sanction.

Copy of letter No.401(3) dated 24-3-1919 from the General Electric Inspector to the Chief Electrical Engineer to the Government of Mysore.



LIGHTNING CONDUCTOR AT BETTADAPUR.

With reference to your personal instruction given to me regarding the Executive Engineer's No.1396 dated 25-7-1918, I have the honour to report that the temple of Mallikarjunaswamy at Bettadapur was inspected, and found to have been severely damaged by frequent strokes of lightning discharges. The temple being situated on the extreme end of a high solitary hill in the midst of an extensive plain ground all round, is thus exposed very frequently to lightning discharges. I am of opinion, that if prompt attention is not taken to guard this old and historical relic against this destruction the whole temple is sure to crumble down to pieces and thus would soon disappear from existence.

I may further say that observation of the lightning conductor attempt made for its repairs or extension, would be of no use until it is guarded by lightning conductor. After a very careful obser-

of the situation, a very efficient and up to date lightning
or installation has been provided.

A probable estimate for which is herewith submitted.

"C O P I E S"

Superintending Engineer,
Western Circle.

K.N.

G. R. S. VI—G/32]

SUBJECT Calls for further information regarding the funds available at the credit of the Sri Mallikarjuna temple at Bettadapura, Hunsur taluk

Diary No. of letter replied to 27 1922-23.

General and Revenue Secretariat

( )

, the 191 .

Section

File No. 35-22

Serial No 2

No. 378

Revenue

Date of issue 24/7/22

Signed by [illegible]

To

The Deputy Commr, Mysore Dt.

Sir,

I am directed to state that an estimate for Rs. 1254 for the installation of a lightning conductor to the Sri Mallikarjuna Swami temple at Bettadapura, Hunsur Taluk, has been received through the Chief Engineer of Mysore and to request that a report may be sent as to if the work is to be done, etc.

over.

Revenue 27 with enclosures

what amount is now available at the credit of the institution and whether the work is being executed as stated by the Chief Electrical Engineer. An early reply is requested.

I have &c.,

Secretary to Govt,
Marine Dept.

24/7/22

List of enclosures.

Copied by

Examined by

A 7c

Rev 35-22-3

19 22

From *The Deputy Commissioner,*
Mysore District.

To *The Secretary to the Government*
of Mysore, Bangalore.
Revenue Department.

Dated 17th August 1922

Despatched 18th August 1922

Received

General No. 2012 /22 23. Revn

No.

Enclosure No.

Subject

Submits report regarding the installation of lighting Conductors to the Sri Mallikarjuna temple at Talakad [illegible]

ST

9906 No. 25

OFFICE OF THE DEPUTY COMMISSIONER,
MYSORE DISTRICT,

Dated, Mysore, ...16th..August ..1922.....192

17

From

P.F. Bowring, Esq.,
Deputy Commissioner, Mysore District.

To

T.E. Jayarama Iyer, Esq., B.A.,B.L.,
Secretary to the Government of His Highness
the Maharaja of Mysore, Bangalore.
Revenue Department.

SIR,

With reference to your letter No.375/Muz. 35-22-2 dated 24th July 1922, I have the honor to state that the installation of a lightening conductor to the Sri Mallikarjunaswami Temple at Bettadapur, Hunsur Taluk, is reported by the Sub Division Officer, Mysore, to be necessary and that it may be installed. Further the Amildar says that there is no objection taken by the villagers to the proposed installation.

A sum of Rs.4832-0-0 is said to be available at the credit of the institution in question.

I have the honor to be,

Sir,

Your most obedient servant,

For Deputy Commissioner,
Mysore District.

19

G.R..S VI G 34]

SUBJECT Sanctions an estimate for Rs. 1254 for the installation of a lightning conductor to the Sri Mallikarjunaswami temple at Bettadapur, Hunsur Taluk.

Diary No. of letter replied to 700 of 22-23.

Section

File No. 3[illegible]-22

Serial No. 4

General and Revenue Secretariat

( )

, *the* 192 .

Proceedings of the Government of His Highness the Maharaja of Mysore.

Date of issue 8-9-22

Signed by [illegible]

Read— Letter No. B. 389 dated 15 July 1922 from the Chief Engineer of Buildings forwarding for sanction an estimate for Rs. 1254 for the installation of a lightning conductor on the Sri Mallikarjunaswamy temple at

Order Thereon No.

at Bettadapur, Hunsur Taluk

[illegible]

May this be

i Printed ?

ii treated as a standing order ?

iii published in the Gazette, English Part ?

iv translated ?

v placed at the disposal of the press ?

vi published in the Gazette, Kannada Part ?

that the temple being situated on a high hill is frequently exposed to attacks of lightning discharges and that prompt attention is necessary ~~to fit~~ to ground the temple against the danger. ~~it is best to assemble down to fees~~

& Correspondence ending with letter No. R2 dated 16th August 1922, from the Deputy Commissioner, Mysore, stating that the installation of lightning conductors is necessary and stating that a sum of Rs. 400/- is available at the credit of the institution.

Order No. 1149-51 dated

Estimate for Rs. 1814 is hereby accepted for charge being taken from the funds at the credit of the institution.

List of enclosures.

Copied by Reel 5.9.22

Examined by

By Secretary to Govt. Revenue Dept.

To The Chief Engineer & Inspector, with the Govt. estimate & other enclosures.
The Dy Commissioner, Mysore, through the Executive Engineer, Mysore.
He is requested to submit a report for the work and estimate.

Abstract of estimate for providing the lightning conductor to the Mallikarjunaswami temple at Bettadapur, Hunsur Taluk.

Description.	Quantity	Rate	Per	Amount.
1. Conductor rods @ 6' long 1" dia. with platinum points of prove terminalst coupling complete.	3	40 0 0	each	120 0 0
2. Copper tape 1 x 1/8"	1000 ft.	0 8 0	foot	500 0 0
3. Rivets (copper)	10 Doz.	0 6 0	Doz.	3 12 0
4. Clamps. do.	10 do.	4 8 0	do.	45 0 0
5. Galv.pipe @ 2" dia.10' long with pointed ends.	6	22 0 0	each	132 0 0
6. Support for finials	3	Lump sum		50 0 0
7. No. 6 copper wire	100 ft.	1 0 0	10 ft.	10 0 0
8. Solder, paste, emery cloth &c.		Lump sum		25 0 0
9. Sand	4 carts load	2 0 0	each	8 0 0
10. Coke	½ ton	110 0 0	ton	55 0 0
11. Labour				130 0 0
12. Freightage to the top of the hill				100 0 0
13. Tinning the earth conductors				25 0 0
14. Contingencies at 5%				59 11 0
				1253 7 0
		or Rs.1254.		

"Copy"

[signature]

Secretary to Government,

Revenue Department.